FY20 – PAVEMENT SCOPE OF SERVICES

PROJECT NAME:	PIC-SR 316/752-13.05/0.000	PID: 107824
County:	Route:	SECTION:
PIC	316	13.05-13.68
PIC	752	0.00-1.74
PIC	752	1.92-8.43

1. PROJECT IDENTIFICATION:

PIC-SR 316 – 13.05-13.68 Functional Class: 05 – Major Collector (Rural) PIC-SR 752 – 0.00-1.74 Functional Class: 05 – Major Collector (Rural) PIC-SR 752 – 1.92-8.43 Functional Class: 05 – Major Collector (Rural)

2. PURPOSE AND NEED:

PIC-316-13.05-13.33 was last maintained in 2010 by PID 83638. This route is currently displaying deteriorations including raveling (LO), rutting (LO), transverse cracks (MF), edge cracking (MF) and crack seal deficiencies (O). Resurfacing and repairs are needed on this route to ensure pavement integrity and to provide the traveling public with safe driving surfaces.

PIC-316-13.05-13.33 2017 PCR: 79

2017 Structural Defect: 12.0

Note: This section of pavement is composite pavement.

PIC-316-13.33-13.68 was last maintained in 2010 by PID 83638. This route is currently displaying deteriorations including raveling (LO), crack seal deficiencies (E), rutting (LO), traverse cracks & an unjointed base (MF), wheel track cracks (LO), block and transverse cracking (LO), longitudinal joint cracks (flexible pavement widening crack) (MF), thermal cracks (MO). Resurfacing and repairs are needed on this route to ensure pavement integrity and to provide the traveling public with safe driving surfaces.

PIC-316-13.33-13.68 2017 PCR: 81

2017 Structural Defect: 7.3

Note: This section of pavement is flexible pavement.

PIC-752-0.00-1.74 was last resurfaced in 2007 by PID 25600. PIC-752-1.92-8.43 was last maintained in 2007 by PID 79313. This route is currently displaying deteriorations including raveling (LO to MO), crack seal deficiencies (E, F, and O), rutting (LF to LO), wheel track cracks (LO), block and transverse cracking (LO), longitudinal joint cracks (LO, MF, and MO), edge cracking (LO to MO), and thermal cracks (MO). Resurfacing and repairs are needed on this route to ensure pavement integrity and to provide the traveling public with safe driving surfaces.

PIC-752

2017 PCR: 76 to 98

2017 Structural Defect: 0.0 to 10.8

Note: This section of pavement is flexible pavement.

3. PROJECT INITIATION PACKAGE:

Yes ⊠

No □

Site visit conducted 5/22/18 with Dave Rankin, Scott Rice, Tim Peddicord, Bob Mcneill, Grace Wesner, Frank Christman and Chris Tebbe.

All noted red flags from field visits contained within scope.

4. PROJECT LIMITS:

From: PIC-316-13.05 (Jefferson Avenue)
To: PIC-316-13.68 (Station Street)
Project Length: 0.63 centerline miles
Work Length: 0.63 centerline miles

From: PIC-752-0.00 (*Intersection with US 23*)

To: PIC-752-1.74 (0.01 mile West of Poplar Street)

Project Length: 1.74 centerline miles Work Length: 1.74 centerline miles

From: PIC-752-1.92 (0.10 mile East of Intersection with SR-316)

To: PIC-752-8.43 (Intersection with SR 674)

Project Length: 6.51 centerline miles Work Length: 6.51 centerline miles

Total Project Length: 8.88 centerline miles
Total work Length: 8.88 centerline miles

The following sections are inside a Village:

The Village of Ashville:

- PIC-316-13.05 to 13.68
- PIC-752-0.90 to 0.98
- PIC-752-1.19 to 1.31
- PIC-752-1.58 to 2.32

5. GENERAL DESCRIPTION OF WORK:

1325 yd²

Item 251-Partial Depth Pavement Repair (Asphalt Concrete Base), As Per Plan: Repair areas shall be determined by the project engineer before the beginning of work. Repairs shall consist of removing 3" of pavement and placing 3" of Item 301 – Asphalt Concrete Base, PG64-22. Work shall be performed prior to resurfacing and repair areas are to be included into general resurfacing. To Be Determined with Pavement Engineer/County Manager during detailed field review.

Designer Note:

- At PIC-752-1.37: repair needs to be included over top of the concrete capped culvert (under RR bridge)
- Approximately 1% of the surface area of PIC-752 is to be repaired with this project using Item 251 repair type.
- Final locations and quantities need to be requested by the designer at least 1 month prior to Stage 3 file date.

 $XXyd^2$

Item 251-Partial Depth Pavement Repair (Asphalt Concrete Base), As Per Plan: Repair areas shall be determined by the project engineer before the beginning of work. Repairs shall consist of removing 5" of pavement and placing 5" of Item 301 – Asphalt Concrete Base, PG64-22. Work shall be performed prior to resurfacing and repair areas are to be included into general resurfacing. To Be Determined with Pavement Engineer/County Manager during detailed field review.

Designer Note:

- This quantity is to be used to correct some of the bad edge failure along SR-752.
 - o Some spots of edge failure within the Village of Ashville corp limits
- Final locations and quantities need to be requested by the designer at least 1 month prior to Stage 3 file date.

TBD yd²

Item 253- Pavement Repair, As Per Plan:

Repair areas shall be determined by the project engineer before the beginning of work. Repairs shall consist of removing X"-X" of pavement and placing X" of Asphalt on X" of Item 304. Work shall be performed prior to resurfacing. To Be Determined with Pavement Engineer/Village during detailed field review.

Designer Note:

- This repair type is to be used on SR-316
 - o These repairs are intended to be adjacent to the curb and gutter replacement
 - O Started with 2' wide repairs, but in agreement with the Village, a wider repair may be more beneficial
- One spot of base failure along SR-752 within the Village of Ashville limits
 - ~SLM 1.89 heading East at the new intersection with SR-316
 - Heavy trucks damaged the new pavement
 - The Village requests that this repair be included with this project, but is going to check if this can get funded some other way

General Work to be performed on PIC-316:

1.5" Item 254 – Pavement Planing, Asphalt Concrete (check with Village if they want milled material)

1.5" Item 441 – Asphalt Concrete Surface Course, Type 1, PG64-22

Item 407 – Non-Tracking Tack Coat

*Potential for variable depth milling to reduce the centerline pavement thickness and flatten the cross slope in order to maximize curb reveal/preserve the curb

General Work to be performed on PIC-752-0.05-5.09 & 5.27-8.43:

1" Item 897 – Fine Planing, Class A

1" Item 424 – Fine Graded Polymer Asphalt Concrete, Type B

Item 407 – Non-Tracking Tack Coat

Item 617 – Compacted Shoulder Aggregate (average 2" deep and 1' wide)

Safety Edge

General Work to be performed on PIC-752-0.00-0.05 (rutted at intersection with US-23) & PIC-752-5.09-5.27 (rutted at intersection with Winchester Road):

3" Item 254 – Pavement Planing, Asphalt Concrete

3" Item 442 – Asphalt Concrete Surface Course, 12.5mm, Type A (446), PG76-22M

Item 407 – Non-Tracking Tack Coat

Item 617 – Compacted Shoulder Aggregate (average 2" deep and 1' wide) Safety Edge

N	o	t	e	S
Τ.	v	u	v	o

(1). Butt joints begin/end of project, at milling limits,	and bridges not being paved over.	Not intended to include
butt joints at paved driveways.		

- (2). Item 623 Monument Box Adjusted to Grade 4 each
- (3) Item 611 Manhole Adjusted to Grade 4 each
- (4). Item 638 Valve Box Adjusted to Grade 4 each
- (5). Curb and gutter replacement on SR-316 within the Village of Ashville locations where necessary The Village intends to raise the curb and gutter (and sidewalk) in areas where this is possible. Curb and gutter will be replaced (along with full depth pavement repairs along the curb line) where the curb and sidewalk cannot be raised. Locations and quantities will be determined once survey has been completed and additional pavement coring.
- (6). Existing Plans, Copy of Destape, and SLD's have been placed in following location in project folder: I:\ProjectData\107824_PIC-316-13.05\ProjAdmin\Planning\Scopes\Existing Info
- 6. PRIOR STUDIES/PLAN (IDENTIFY):

PID 83638	PIC-316-13.05-13.68	0.75" Item 424 Fine Grade Polymer Concrete, Type B
PID 17000	PIC-316-13.05-13.68	0.75" Item 448 Intermediate, 1.25" Item 448 Surface
PID 79313	PIC-752-1.82-8.43	0.75" Item 424 Fine Grade Polymer Asphalt Concrete,
Type B Heavy		• •
PID 17000	PIC-752-1.82-8.43	0.75" Item 448 Intermediate, 1.25" Item 448 Surface
	PID 79313 Type B Heavy	PID 17000 PIC-316-13.05-13.68 PID 79313 PIC-752-1.82-8.43 Type B Heavy

^{*}County crews chipsealed SR-752 from the Eastern Ashville corp to SR-674

Yes 🖂

7.	DESIGN SPE	ED: PIC-33 PIC-75		5 mph (25 mp 5 mph (35 mp	oh in Ashville) h in Ashville)	
8.	ALIGNMENT:	New 🗌	Existing	⊠ Combin	nation \square	Journalized Alignment
9.	PROFILE:	New □	Combina	tion 🗆	Salvage ⊠	
10.	. SCHEMATIC PL	AN: Yes ⊠	l N	lo □		

No \square

12. TRAFFIC DATA:

11. TYPICAL SECTION:

	CURRENT TRAFFIC (PIC 2016)		OPENING DAY (2020)		DESIGN YEAR (2032)	
	ADT	ADTT	ADT ADTT		ADT	ADTT
PIC-316-13.05- 13.68	4339	93.24	4700	94	4800	96
PIC-752-0.00- 8.43	4875	341.25	5200	364	6300	441

13.	Crash Analysis:	Yes ⊠	No 🗆	Possible ☐ (To	Be Determined)				
	This project does require a crash analysis for SR-316. An email requesting the crash analysis was sent on 5/29/18 to the D6 Safety Team, and a response was requested by 6/12/18. Any recommendations based on the results of the crash analysis have been added to the scope. A copy of the crash analysis has been placed within the project planning folder.								
	SR-752 is consider	red a surface treat	ment and no cras	sh analysis is rec	juired.				
14.	TYPE OF ACCE	SS:	Limited □	Controlled \square	Non-Controlled \boxtimes				
15.	FENCING:		Yes □	No ⊠					
16.	LIGHTING:		Yes □	No ⊠					
17.	SIGNING:		Yes 🗵	No 🗆					
	 Sc Cr M W SR-752: C Sc 	project?) ain/Long Street: 2 right Street: 2 pecturves at ~SLM 4.	pedestrian crossic edestrian crossic nanent stop sign the no pedestrian collectrian crossing 36	ng signs needed here, as well (we rossing signs needed	cill the Village replace this prior to the eded Replace with this project or do it				
18.	GUARDRAIL:		Yes ⊠	No 🗆 Possible	e □ (To Be Determined)				
19.	SIGNALS:		Yes ⊠	No Desible	e 🗌 (To Be Determined)				
	warranted	•			e three signals along SR-316 are				
	o Th	•	sections are the set and SR-316	signals that need	a warrant analysis:				

Page **5** of **5**

o The Village wishes to incorporate safe crosswalk upgrades if the signals are not warranted

SR-316 at Main and Long Streets

Scioto Street and SR-316

*Signal warrant request sent on 5/24/18		
20. PAVEMENT MARKING: PIC-316/752 Item 644 – Thermoplastic Pave Item 646 – Epoxy Pavement M The epoxy needs to be alternate	arking (for all co	Q ,
All center lines shall be 4". All		
o This is a flashing c	xisting ladder crorswalk to get t	along SR-316 and SR-752: osswalk striping across SR-752 o and from Teays Valley High School replaced with standard crosswalk?
Include school markings and R	R striping with the	his project.
Replace stop bars where they as - Only replace if they were in		
Designer Note: - PIC-752 is not a truck rout	e, so lanes need	to be striped at 10' wide
21. DELINEATION:		
Barrier Reflectors:	Yes ⊠	No □
Delineators:	Yes 🗆	No ⊠
Raised Pavement Markers: There are no special RPMS nee	Yes ⊠ ded for PIC-316	No □ -13.05-13.68.
		00-8.43. Follow the link below to see the specifications 816-13.05\ProjAdmin\Planning\Scopes\Existing
22. ROADSIDE DEVELOPMENT:	Yes □	No ⊠
23. REST AREAS:	Yes □	No ⊠
24. DRAINAGE/CULVERTS:	Yes ⊠	No \square Possible \square (To Be Determined)
b. Aggregate drains need to be insc. Drainage work to be included v	talled in all full within the Village	
25. INTERCHANGES:	Yes □	No ⊠

26. BRIDGES (Tim Peddicord):	Yes ⊠	No □	Possible [☐ (To Be Determined)	
If applicable see attached Bridg	e Scope of Wo	rk			
27. INVESTIGATE PREFABRICAT	ED STRUCT	URE:	Yes □	No ⊠	
28. SUBSURFACE INVESTIGATIO	N:		Yes □	No ⊠	
29. BIKEWAYS:			Yes □	No ⊠	
30. MASS TRANSPORTATION:			Yes □	No ⊠	
SLM 1.58. Agreement will be out with "Begin In-House Designation of the Begin In-House Designation of the	required. Init gn'' submittal.	tial coordi	nation sho	No □ g at PIC-316 SLM 13.29 and PIC uld begin immediately and be set	
Note: There is an abandoned R.	K that crosses I	PIC-310 a			
32. SERVICE ROADS:			Yes \square	No ⊠	
33. SIDE ROADS:Pavement at all approaches should e beyond the edgeline with the followSR-316:	ring exceptions	:	·		20'
- SR-752: o Walnut Creek Pike: North Side o Winchester Road – Designer to Ett-Noecker Road -	has been paved pave back to po provide pland pave back to provide pland Road: has been paved	d recently avement by sheets at the pavement sheets at the large and the large are the large are the large are large	— match broreak on eithis intersed break on eithis intersed his intersed — match br	ther side of the intersection ection either side of this intersection ection	
34. RETAINING WALLS:			Yes □	No ⊠	
35. NOISE WALL:			Yes □	No ⊠	
36. AERIAL PHOTOGRAPHY AND	OOR MAPPIN	NG:	Yes □	No ⊠	
 37. FIELD SURVEYS: Yes ⋈ No ☐ Possible ☐ (To Be Determined) No internal field survey is needed. The Village of Ashville plans to perform additional survey work along SR-316. 					

38. MAINTENANCE OF TRAFFIC	:	Yes ⊠	No 🗆	
No lane closure hour restrictio coordination with MOT Engin		s anticipated to be	single lane via flagge	ers. Final
LEO hours need included at al	1 signalized inters	sections.		
39. MAINTENANCE OF PEDESTI	RIAN TRAFFIC	: Yes □ No □ Po	ssible ⊠ (To Be Det	termined)
V/Gary – do we need to incorp with this project?	orate maintenanc	e of pedestrian traf	fic when working on	the sidewalk
40. MAINTENANCE OF RAILROA Designer to coordinate with N Agreement will be required. If In-House Design" submittal.	orfolk Southern fo			
41. ADDITIONAL SAFETY IMPRO	OVEMENTS:	Yes □ No □ Po	ossible 🛛 (To Be De	termined)
42. R/W ACQUISITION ANTICIPA	ATED:	Yes 🗆	No ⊠	
43. R/W ENCROACHMENT:	Yes ⊠	No □ P	ossible 🗆 (To Be D	etermined)
- SR-752: ○ House #3660 – br	ick mailbox – is tl	his an encroachmer	ıt?	
44. UTILITY IMPACTS ANTICIPA	ATED: Yes □	No □ Possible □	(To Be Determined	(<mark>t</mark>

A more detailed survey is being conduction by the Village of Ashville along SR-316. Once the survey has been completed, it will be easier to determine whether or not utilities will be impacted.

No utilities will be impacted along SR-752.

- 1. No utility impact anticipated on this project due to the scope of the work in relation to the proximity to the existing utilities within the construction limits of the project.
- 2. All aerial crossings of utilities will need to be taken into consideration because they will remain during project.
- 3. If any depth of pavement changes, take underground utilities into consideration at the impacted station locations if applicable.
- 4. All guardrail replacements must be placed in the same location or it is the expectation of the contractor to place the guardrail in locations that do not cause conflicts with underground utilities.

Designer Note – Please add the following plan note – **UTILITIES:**

THE ODOT CONTRACTOR IS REQUIRED TO CONTACT OUPS A MINIMUM OF 48 HOURS EXCLUDING WEEKENDS AND HOLIDAYS TO PERMIT ALL UNDERGROUND UTILITIES AN OPPORTUNITY TO MARK THEIR LINES. IT IS ALSO THE ODOT CONTRACTOR'S RESPONSIBILITY TO CONTACT ALL NON-MEMBERS OF OUPS DIRECTLY A MINIMUM OF 48 HOURS' NOTICE EXCLUDING WEEKENDS AND HOLIDAYS TO PROVIDE THEM WITH THE SAME OPPORTUNITY.

IT IS ODOT'S EXPECTATION THAT ALL GUARD RAIL POSTS WILL BE INSTALLED IN THE SAME LOCATIONS AND THERE WILL BE NO DISRUPTION TO UNDERGROUND UTILITIES. IF THERE IS A UTILITY MARKING WITHIN THE TOLERANCE ZONE OF A UTILITY LOCATE FROM THE PROPOSED GUARDRAIL PLACEMENT IT IS THE ODOT CONTRACTORS RESPONSIBILITY TO DIRECTLY CONTACT THE IMPACTED UTILITY AND WORK WITH THEM TO FIND A SOLUTION THAT DOES NOT CHANGE THE GUARDRAIL PLACEMENT OR DAMAGE THE EXISTING UTILITY. NO UTILITY RELOCATION WILL BE REIMBURSED NOR WILL DELAY CLAIMS BE PERMISSIBLE BASED ON ON LACK OF COORDINATION BETWEEN THE ODOT CONTRACTOR AND THE IMPACTED UTILITY.

45. ENVIRONMENTAL DOCUMENT TYPE ANTICIPATED:

C1	\boxtimes
C2	
D1	
D2	
D3	
Other Higher L	evel Document

46. PROJECT LIMITS WITHIN FLOODPLAIN: Yes \square No \boxtimes

Due to the Environmental Document being a Level C1 – it does not matter if the project is located within a floodplain. If the environmental document level changes, then existing floodplains will need to be researched.

47. ENVIRONMENTAL ISSUES ANTICIPATED:

48. COMPLETE STREETS CONSIDERATION: Yes \boxtimes No \square

ADA Curb Ramps required at crosswalk locations within Village Limits.

- There are ~34 curb ramps that need upgraded along SR-316 with this project
 - o Jefferson Avenue: 4 curb ramps
 - 1 spot with a steep grade may need to redo sidewalk at this corner
 - o Scioto Street: 2 landing pads and curb ramps
 - Cromley Street: potential spot for CDBG intersection upgrade
 - 2 ramps needed on the North side of the intersection
 - 2 new ramps and crosswalk (across SR-316) because the sidewalk ends on the South side of the intersection
 - o RR Tracks: 2 curb ramps needed on the North side (no sidewalk on the South side)
 - o Main and Long Street: replace all 4 curb ramps
 - o Wright Street: Replace all 4 curb ramps
 - Church Street: Replace 2 curb ramps
 - Madison/Plum Street:
 - The Village has requested potentially placing RRFB crosswalks in two locations at this intersection because there is low visibility is this possible?
 - Replace 4 curb ramps
 - o Cherry Street: Replace 2 curb ramps
 - o Harrison Street: Replace 2 ramps
 - Station Street: West side of the intersection is getting upgraded with CDBG funding

2 curb ramps needed on the	he East side of the inters	ection
49. NHS ROUTE:	Yes □	No ⊠
50. FEDERAL TRUCK ROUTE (FAP):	Yes □	No ⊠
 51. DRIVEWAYS: This project shall include items for the paving of drive the existing conditions. If the apron is asphalt then pathen use Item 617. (Typically - 5'(ex. Asphalt), 5'(ex On SR-316: the Village of Ashville wishe the intent with this project? On SR-752: pave the driveway aprons usi 	ave it with mainline pave aggregate), 2' (ex conc s to have driveway apro	ement. If the apron is aggregate crete). ns paved with concrete. Is this still
52. MAILBOX APPROACHES: This project shall include items for the paving of maill existing conditions – if it is asphalt pave it, if it is aggregations.		No \square all mailboxes shall pave to
53. ITS (Nick Hegemier):	Yes □	No ⊠
54. RWIS Sensor:	Yes □	No ⊠
55. ATR:	Yes □	No ⊠
56. LEGISLATION:	Yes ⊠	No □
This project goes through the Village of Ashvi - This project will require funding from the pavement repairs along SR-316. Only conthe amount of participatory legislation is seen to be a part 1/Part 2 project - This will be a Part 1/Part 2 project - The Village of Ashville will compefforts such as the curb and gutter pavement repair locations, along very	Village of Ashville for a sent legislation may be unknown from the Village Yes ⊠ No □ Possiplete the design for SR-3 replacement, any drains	drainage upgrades, along with needed for SR-752. At this time, ge of Ashville. ble □ (To Be Determined) 316 because of the heftier design age work and the full depth
58. DELIVERABLES REQUIRED (but not limited	d to):	
 Prelim Coordination Plan (Env and R. Stage 3 Plan for Review Final Plan Package 	/R)	

All Project Development to follow the current version of the ODOT Plan Development Process and applicable

Design Manuals.

CULVERT SCOPE OF WORK

3.0 Culvert:

3.0.0 Source Layer: TIMS Assets\TIMS.TIMS.WGIS_CULVERT 3.0 Culvert 1

ulvert 1	
Association Type: Along 1	Linear Project
Distance to Project Segment: 0.0 met	ters
3.1.1 [CULVERT_FILE_NUMBER]	1836593
3.1.2 [CRS]	PIC-752-7.739
3.1.3 [NLFID]	SPICSR00752**C
3.1.4 [COUNTY_CD]	PIC
3.1.5 [ROUTE_TYPE]	SR
3.1.6 [ROUTE_NBR]	00752
3.1.7 [CTL_BEGIN_NBR]	7.739
3.1.8 [CRS]	PIC-752-7.739
3.1.9 [CULVERT_OWNER]	\mathbf{S}
3.1.10 [FEATURE_INTERSECTED]	-
3.1.11 [STATUS]	\mathbf{A}
3.1.12 [CULVERT_SHAPE]	1
3.1.13 [MATERIAL]	2
3.1.14 [SPAN_INCHES]	12
3.1.15 [RISE_INCHES]	12
3.1.16 [LENGTH_FEET]	44
3.1.17 [MATERIAL_CONDITION]	6
3.1.18 [CULVERT_ALIGNMENT]	7
3.1.19 [SHAPE_RATING]	None
3.1.20 [SEAMS_OR_JOINTS]	None
3.1.21 [SLAB]	None
3.1.22 [ABUTMENTS]	None
3.1.23 [SCOUR]	None
3.1.24 [GENERAL_APPRAISAL]	5
3.1.25 [COMMENT_INSP]	Crushed pipe ends
3.1.26 [INSPECTION_DATE]	2017-02-01 13:38:11

- Can the county perform the work on this culvert prior to the project?

BRIDGE SCOPE OF WORK

2.0 Bridge 1

Association Type: Along Linear Project Distance to Project Segment: 0.0 meters 2.1.1 [SFN] 6503608 2.1.2 [NLFID] SPICSR00752**C **2.1.3** [COUNTY_CD] PIC **2.1.4** [ROUTE_TYPE] SR 2.1.5 [ROUTE_NUMBER] 00752 2.1.6 [CTL_BEGIN_NBR] 0.54 **2.1.7** [DECK_AREA] 1712 2.1.8 [MAIN_STRUC_TYPE] 112 2.1.9 [FEATURES INTERSECTED] **MUD RUN** 2.1.10 [STRUCTURE_LENGTH] 53.5 **2.1.11** [WEAR_SURF_DT] 2001-08-17 00:00:00 2.1.12 [TYPE_OF_WEARING_SURFACE] C 2.1.13 [WEARING_SURF_CONDITION_RATING] 1 2.1.14 [GEN_APPR_CONDITION_RATING] 2.1.15 [BRIDGE_RAILINGS] 1

- Washout on the NE corner of the GR run
- Seal with GFR
- Some minor cracking on the bridge deck
- Pave up to the bridge deck

2.5 Bridge 6

Association Type:	Along Linear Project
Distance to Project Segment:	0.0 meters
2.6.1 [SFN]	6503632
2.6.2 [NLFID]	SPICSR00752**C
2.6.3 [COUNTY_CD]	PIC
2.6.4 [ROUTE_TYPE]	SR
2.6.5 [ROUTE_NUMBER]	00752
2.6.6 [CTL_BEGIN_NBR]	1.34
2.6.7 [DECK_AREA]	1539
2.6.8 [MAIN_STRUC_TYPE]	321
2.6.9 [FEATURES_INTERSECTED]	UNDER CSX RR
2.6.10 [STRUCTURE_LENGTH]	32.0
2.6.11 [WEAR_SURF_DT]	1986-01-01 00:00:00
2.6.12 [TYPE_OF_WEARING_SURFACE]	N
2.6.13 [WEARING_SURF_CONDITION_RATING]	
2.6.14 [GEN_APPR_CONDITION_RATING	4
2.6.15 [BRIDGE RAILINGS]	N

- Do not reduce vertical clearance
- There is currently flooding under this bridge

- County crews are upgrading the drainage structures underneath and working to get water to the creek
- They are adding new sensors to detect flooding under the bridge so that the high water sign with flash its lights sooner
 - Cameras will be added and the sensors will send an email notification to a group of people to notify them that there is flooding and help determine if the road needs closed sooner

2.1 Bridge 2

Association Type:	Along Linear Project
Distance to Project Segment:	0.0 meters
2.2.1 [SFN]	6503675
2.2.2 [NLFID]	SPICSR00752**C
2.2.3 [COUNTY_CD]	PIC
2.2.4 [ROUTE_TYPE]	SR
2.2.5 [ROUTE_NUMBER]	00752
2.2.6 [CTL_BEGIN_NBR]	3.34
2.2.7 [DECK_AREA]	8740
2.2.8 [MAIN_STRUC_TYPE]	322
2.2.9 [FEATURES_INTERSECTED]	WALNUT CREEK
2.2.10 [STRUCTURE_LENGTH]	273.0
2.2.11 [WEAR_SURF_DT]	1992-01-01 00:00:00
2.2.12 [TYPE_OF_WEARING_SURFACE]	2
2.2.13 [WEARING_SURF_CONDITION_RA	ATING] 1
2.2.14 [GEN_APPR_CONDITION_RATING	3] 8
2.2.15 [BRIDGE_RAILINGS]	1

- Seal the deck with non-epoxy sealer
- Replace strip seal glands within steel joints
- Investigate jacking up the approach slab
 - o Run smoothness over?
 - o The approach slabs are dipping at both ends

2.4 Bridge 5

Association Type:	Along Linear Project	
Distance to Project Segment:	0.0 meters	
2.5.1 [SFN]	6503683	
2.5.2 [NLFID]	SPICSR00752**C	
2.5.3 [COUNTY_CD]	PIC	
2.5.4 [ROUTE_TYPE]	SR	
2.5.5 [ROUTE_NUMBER]	00752	
2.5.6 [CTL_BEGIN_NBR]	4.61	
2.5.7 [DECK_AREA]	1539	
2.5.8 [MAIN_STRUC_TYPE]	231	
2.5.9 [FEATURES_INTERSECTED]	BEAR RUN CREEK	
2.5.10 [STRUCTURE_LENGTH]	51.2	
2.5.11 [WEAR_SURF_DT]	2000-06-08 00:00:00	
2.5.12 [TYPE_OF_WEARING_SURFACE]	6	
2.5.13 [WEARING_SURF_CONDITION_RATING] 1		
Page 14 of 14		

2.5.14 [GEN_APPR_CONDITION_RATING] 9 2.5.15 [BRIDGE_RAILINGS] 1

- Pave over
- Saw and seal joints at 4 locations

2.2 Bridge 3

Association Type:	Along Linear Project
Distance to Project Segment:	0.0 meters
2.3.1 [SFN]	6503713
2.3.2 [NLFID]	SPICSR00752**C
2.3.3 [COUNTY_CD]	PIC
2.3.4 [ROUTE_TYPE]	SR
2.3.5 [ROUTE_NUMBER]	00752
2.3.6 [CTL_BEGIN_NBR]	6.87
2.3.7 [DECK_AREA]	538
2.3.8 [MAIN_STRUC_TYPE]	395
2.3.9 [FEATURES_INTERSECTED]	MIMONI DITCH
2.3.10 [STRUCTURE_LENGTH]	15.0
2.3.11 [WEAR_SURF_DT]	2000-06-08 00:00:00
2.3.12 [TYPE_OF_WEARING_SURF	FACE] N
2.3.13 [WEARING_SURF_CONDITI	ON_RATING]
2.3.14 [GEN_APPR_CONDITION_R	ATING] 4
2.3.15 [BRIDGE_RAILINGS]	N

- Pave over
- The bottom of the pipe was recently paved
 - o The GA rating will go up now

2.3 Bridge 4

Association Type:	Along Linear Project	
Distance to Project Segment:	0.0 meters	
2.4.1 [SFN]	6503748	
2.4.2 [NLFID]	SPICSR00752**C	
2.4.3 [COUNTY_CD]	PIC	
2.4.4 [ROUTE_TYPE]	SR	
2.4.5 [ROUTE_NUMBER]	00752	
2.4.6 [CTL_BEGIN_NBR]	7.44	
2.4.7 [DECK_AREA]	646	
2.4.8 [MAIN_STRUC_TYPE]	395	
2.4.9 [FEATURES_INTERSECTED]	PAINTER RUN	
2.4.10 [STRUCTURE_LENGTH]	23.0	
2.4.11 [WEAR_SURF_DT]	2000-06-08 00:00:00	
2.4.12 [TYPE_OF_WEARING_SURFACE]	N	
2.4.13 [WEARING_SURF_CONDITION_RATING]		
2.4.14 [GEN_APPR_CONDITION_RATING	8	
2.4.15 [BRIDGE_RAILINGS]	1	

- Pave over

GUARDRAIL SCOPE OF WORK

PIC-316

No guardrail work needed on PIC-316 between SLM 13.05 – 13.68.

PIC-752

ADT: ???? (6,300)

The determination of the "overall" condition of guardrail on this section of SR-752 would rate <u>less than decent</u>. Did not encounter any sections that were exceedingly low. All Anchor Assemblies were type A's and would warrant upgrading according to the ADT in the scope (6,300). However it was discussed that the 6,300 ADT may not apply to most of the areas where the guardrail is located and that 6,300 ADT is the high count at US-23. My evaluation would lean towards total upgrades and replacements but I will defer the final decision to Planning, where actual ADT and funding availability can be evaluated.

PIC-752-0054 (BRIDGE) (both sides)

- Overall condition: "Less than Decent"
 - Small "washout" next to bridge
 - Old style BTA's to be upgraded to Type 4
 - Guardrail old and beat up
 - Existing Type A anchors
 - Overall Ex. Bridge railing DBR OK (Do not Retro) but would recommend replacing bridge panels (only) they show wear and age.

PIC-752-3.05 (both sides)

- Overall condition: "Less than Decent"
 - Existing Type A anchors
 - o Ex. Guardrail wrapping around Hoover Rd. all new do not disturb the radius. (tie into)
 - o All guardrail on the state route low, old and beat up

*There is a washout under the GR on the NW side of this run

Matt/Jon – Could you provide input on what to do?

PIC-752-3.19 - 3.25 (both sides)

- Overall condition: "Less than Decent"
 - Existing Type A anchors
 - o Ex. Guardrail is tall enough (maybe too tall)

*There are washouts under this GR run on both the North and South sides. There would be room to pave a wider shoulder on the North side.

Matt/Jon – Could you provide input on what to do?

PIC-752-0344 (BRIDGE) (both sides)(over Walnut Creek)

- Overall condition: "Less than Decent"
 - Good on bridge need reflectors added

Page **16** of **16**

- o Ex. Type 4 BTA's pretty good
- o All rail off the bridge low, beat up, old
- Existing Type A anchors

PIC-752-4.36 (outside curve only)

- Overall condition: "Less than Decent"
 - Existing Type A anchors
 - o old and beat up

PIC-752-0461 (BRIDGE) (both sides)

- Overall condition: "Less than Decent"
 - Old style BTA's to be upgraded to Type 4
 - o Guardrail old and beat up
 - Existing Type A anchors
 - Overall Ex. Bridge railing DBR OK (Do not Retro)

PIC-752-0753 (both sides)

- Overall condition: "Less than Decent"
 - o Huge Offset good may need some grading from EOP to face of GR
 - o Guardrail old (decent) good height
 - Existing Type A anchors
 - o If replacing use long posts both sides or move in 2' if you have to.