

Project Safety Enhancement

Location of Current Tables in
Open Shelter House



Figure 1.



Figure 2.



Figure 3



Figure 4



A cursory look at Figure 1, may not indicate the issue. A closer examination of Figures 2, 3, and 4 will reveal the missing end caps on the top and bench seats. The continued use of these tables has resulted in deterioration. This has created some sharp edges on the tables. We currently use duct tape but this is no longer taking care of the issue. In addition the design of the tables make them prone to tip over if weight is not evenly distributed.

Existing construction standards for park equipment provide for more health and safety.